

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

M-K-T Freight Terminal
(Katy Freight Terminal)
1811 Ruiz Street
Houston
Harris County
Texas

HABS No. TX-3395

HABS
TEX
101-HOUT
6-

Documentation: 19 exterior photos (1992, 1993)
 1 interior photo (1993)
 13 data pages (1993)

Thomas P. Eisenhour, Photographer, October 1992
R. Milton Bell, Photographer, February 1993

TX-3395-1	VIEW OF WEST AND SOUTH FRONTS (1992)
TX-3395-2	VIEW OF SOUTH AND EAST FRONTS (1992)
TX-3395-3	VIEW OF SOUTH FRONT (1992)
TX-3395-4	DISTANT VIEW OF WEST AND SOUTH FRONTS (1993)
TX-3395-5	VIEW OF SOUTH FRONT (1993)
TX-3395-6	VIEW OF EAST FRONT AND SHED (1993)
TX-3395-7	VIEW OF WEST FRONT OF DOCKING BAYS, LOOKING SOUTHEAST (1993)
TX-3395-8	WEST SIDE OF SOUTH FRONT (1993)
TX-3395-9	DETAIL OF MAIN ENTRANCE, SOUTH FRONT (1993)
TX-3395-10	DETAIL OF MAIN ENTRANCE AND DOOR SURROUND, SOUTH FRONT (1993)
TX-3395-11	DETAIL OF LANTERN WINDOW TO EAST OF MAIN ENTRANCE, SOUTH FRONT (1993)
TX-3395-12	DETAIL OF ELEVATION MARKER, MAIN ENTRANCE, SOUTH FRONT (1993)
TX-3395-13	FIRST FLOOR WINDOW, EAST OF MAIN ENTRANCE, SOUTH FRONT (1993)
TX-3395-14	DOCKING BAYS AND AWNING, WEST FRONT, LOOKING NORTHWEST (1993)
TX-3395-15	DOCKING BAYS, AWNING, AND DRAINPIPE, WEST FRONT, LOOKING SOUTHEAST (1993)

TX-3395-16	INTERIOR OF DOCKING BAYS, LOOKING NORTH (1993)
TX-3395-17	SITE VIEW, LOOKING WEST ON RUIZ STREET (1993)
TX-3395-18	SITE VIEW, LOOKING SOUTH ON MCKEE STREET (1993)
TX-3395-19	DETAIL OF EAST SIDELIGHT AND DOOR SURROUND PANEL, MAIN ENTRANCE, AND INTERIOR STAIRCASE (2 1/4 x 1 5/8" negative) (1993)
TX-3395-20	DETAIL OF WEST SIDELIGHT AND DOOR SURROUND PANEL, MAIN ENTRANCE (2 1/4 x 1 5/8" negative) (1993)